## HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

OVERHILLS, HUNT STABLE (Building No. 2) Overhills Historic District East of Nursery Road Fort Bragg Harnett County North Carolina HABS NC-407-A


Martin Stupich, Photographer May 2003		
NC-407-A-1	WALLED CARRIAGE ENTRY, VIEW FROM INSIDE COURTYARD, VIEW TO NORTH	
NC-407-A-2	COURTYARD WALL FROM OUTSIDE COURTYARD, EAST SECTION, VIEW TO SOUTHEAST	
NC-407-A-3	SYMETRICAL VIEW, COURTYARD ENTRANCE FROM OUTSIDE, VIEW TO SOUTH	
NC-407-A-4	COURTYARD WALL FROM OUTSIDE COURTYARD, WEST SECTION, VIEW TO SOUTHWEST	
NC-407-A-5	CENTRAL STRUCTURE WITH DORMERED ROOF, VIEW FROM COURTYARD, TO SOUTH	
NC-407-A-6	EAST STABLE WING FROM WEST SIDE OF COURTYARD, VIEW TO EAST	
NC-407-A-7	DETAIL, WEST STABLE WING, SOUTH HALF, VIEW TO SOUTHWEST	
NC-407-A-8	DETAIL, WEST STABLE WING, NORTH HALF, VIEW TO NORTHWEST	
NC-407-A-9	TYPICAL STABLE DOOR WITH "DUTCH" TOP AND BOTTOM HALVES OPERABLE; WEST SIDE, VIEW TO WEST	S
NC-407-A-10	TYPICAL COLUMN DETAIL WITH WOODEN POST, WOODEN CORBELLED CAP, EAST WING, VIEW TO NORTHEAST	
NC-407-A-11	TWIN SLIDING BREEZEWAY DOORS, CENTRAL SECTION, VIEW TO SOUTH (SEE PHOTO NC-407-A-16 FOR DETAIL OF BAR-RAIL AND ROLLER MECHANISM)	

## OVERHILLS, HUNT STABLE (Building No. 2) HABS No. NC-407-A INDEX TO PHOTOGRAPHS (page 2)

NC-407-A-12	DETAIL OF PAVING PATTERN(S), SHOWING HERRINGBONE CORE, FLAT HEADER EDGE AND DOUBLE-BOX ORNAMENTAL CORNER TREATMENT, VIEW TO SOUTH
NC-407-A-13	TYPICAL VIEW OF COVERED WALKWAY BETWEEN STALLS AND COURTYARD, EAST SECTION, VIEW TO SOUTH
NC-407-A-14	TYPICAL VIEW OF COVERED WALKWAY BETWEEN STALLS AND COURTYARD, WEST SECTION, VIEW TO NORTH
NC-407-A-15	BREEZEWAY, VIEW THROUGH TO COURTYARD, VIEW TO NORTH SHOWING EAST STABLE WING
NC-407-A-16	DETAIL, SLIDER MECHANISM ON COURTYARD BREEZEWAY DOOR VIEW TO SOUTHWEST
NC-407-A-17	GENERAL VIEW, CENTRAL STRUCTURE SHOWING SOUTH FACE AND DORMERS, VIEW TO NORTHWEST
NC-407-A-18	TYPICAL DORMER DETAIL, WEST WING, VIEW TO NORTHWEST
NC-407-A-19	OBLIQUE VIEW OF WEST ELEVATION, VIEW TO SOUTH INTERIOR
NC-407-A-20	CAST CONCRETE DOUBLE SINK, SE UTILITY ROOM, VIEW TO EAST
NC-407-A-21	CAST IRON WATER TROUGH, FORMERLY TYPICAL, NOW RARE EXTANT EXAMPLE, WEST WING, VIEW TO EAST
NC-407-A-22	TYPICAL METAL HAY CRIB, FED FROM LOFT ABOVE, THROUGH FIRE-RESISTANT MASONRY AND CONCRETE CEILING, VIEW TO NORTHEAST
NC-407-A-23	ONCE-TYPICAL ENAMELED STEEL CEILING LIGHT FIXTURE REFLECTOR, WEST WING, VIEW UP AND SOUTHWEST
NC-407-A-24	TYPICAL WOODEN WALL BETWEEN STABLES WITH METAL DIVIDER ABOVE, WEST WING, VIEW TO NORTH
NC-407-A-25	CENTRAL SECTION, PORCH AT N SIDE OF RESIDENTIAL AREA, OPENING ONTO COURTYARD, VIEW TO WEST
NC-407-A-26	ONCE-TYPICAL EXTERIOR DOOR LEADING FROM KITCHEN-HALLWAY TO SOUTH YARD, VIEW TO SOUTHEAST


OVERHILLS, HUNT STABLE (Building No. 2) HABS No. NC-407-A INDEX TO PHOTOGRAPHS (page 3)

NC-407-A-27	KITCHEN, SHOWING INTACT CABINETS, DOORS, TRIM AND (BEYOND) INTERIOR STAIRS, VIEW TO NORTHWEST
NC-407-A-28	LIVING ROOM FIREPLACE, WEST WALL, VIEW TO SOUTHWEST
NC-407-A-29	NARROW WOODEN STAIRS LEADING FROM COURTYARD TO DRESSING ROOM/LOFT ABOVE CENTRAL SECTION, VIEW TO SOUTH (NOTE SMALL TOILET/LAV AT FAR LEFT)
NC-407-A-30	DORMERED LOFT/CHANGING ROOM ABOVE CENTRAL SECTION, WITH LOCKERS IN DISTANCE, VIEW TO WEST



Hunt Stable - Building No. 2 (First Floor Plan)

Photograph Locations



Hunt Stable - Building No. 2 (Second Floor Plan)

Photograph Locations